

Harbour HVAC Service

Victoria, BC
service@harbourhvac.ca

INVOICE

Invoice #	HHS-8821
Date	Jun 3, 2026
Due	Jun 10, 2026

From
Harbour HVAC Service
Victoria, BC
service@harbourhvac.ca

Bill To
Harbour Built Interiors
37 Front Street
Victoria, BC V8W 1Y2

Line items

Description	Amount
Labor	
HVAC diagnostics and rooftop unit reset Qty 1.5 x Rate \$140.00	\$210.00
Materials	
Replacement contactor and control fuse Qty 1 x Rate \$94.00	\$94.00
Other	
After-hours dispatch fee Qty 1 x Rate \$65.00	\$65.00

Subtotal	\$369.00
Tax	\$0.00
Total	\$369.00
Balance due	\$369.00

Registrations

GST: 74291 1845 RT0001

Invoice HHS-8821 (continued)

Description	Amount
Notes / Terms	

Cooling restored during the visit. Recommend a follow-up maintenance check within 30 days if the unit trips again during warmer weather.

Payment instructions

Bank transfer
ACH available on request. Include invoice HHS-8821 in your remittance note.

Card
Pay online using the secure link above.

Pay online

<https://pay.notebill.app/invoice/HHS-8821>